

SPEC SHEET + MEASUREMENTS



Red Kap® Long Sleeve Industrial Work Shirt. SP14

Product photo



Red Kap puts the toughest materials and advanced stay-clean technology into this shirt so you get the most out of it. This hardworking IL50 style is tested through 50 industrial launderer washes.

- 4.25-ounce, 65/35 poly/cotton with Touchtex™ technology which provides breathable comfort lasting colors and stain resistance
- Requires minimal ironing thanks to a wrinkle-resistant finish
- Open collar with sewn-in stays
- Separate two-piece yoke
- 6 button with metal collar gripper closure at neck
- Two button-through pockets
- Bartacked pencil stall on left pocket
- Industrial laundry friendly

CARE INSTRUCTIONS

Machine wash, tumble dry.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



Red Kap® Long Sleeve Industrial Work Shirt. SP14

PRODUCT MEASUREMENTS

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Body Length at Back	31 1/2	31 5/8	31 3/4	31 7/8	32	32 1/8	32 1/4	32 3/8	32 3/8
Chest	21	23	25	27	29	30 1/2	32	33 1/2	35
Pocket Height	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2
Pocket Width	5	5	5	5	5	5	5	5	5
Sleeve Length from Center Back	33	33 1/2	34	34 1/2	35	35	35	35	35

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SPEC SHEET + MEASUREMENTS




Red Kap® Long Sleeve Industrial Work Shirt. SP14

SIZE CHARTS

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Arm	34.25	34.75	35.25	35.75	36.25	36.75	37.25	37.75	38
Chest	34 1/2 - 38	38 1/2 - 42	42 1/2 - 46	46 1/2 - 50	50 1/2 - 53	53 1/2 - 56	56 1/2 - 59	59 1/2 - 62	62 1/2 - 65
Neck	13 5/8 - 14 1/2	14 5/8 - 15 1/2	15 5/8 - 16 1/2	16 5/8 - 17 1/2	17 5/8 - 18 1/2	18 5/8 - 19 1/2	19 5/8 - 20 1/2	20 5/8 - 21 1/2	21 5/8 - 22 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

SPEC SHEET + MEASUREMENTS



Red Kap® Long Sleeve Industrial Work Shirt. SP14

COLORS

Please note: PMS code information is shown only when an exact match is available.



Black
PMS BLACK
C



Charcoal
PMS 7540C



Grey
PMS 409C



Light Blue
PMS 7451C



Light Green
PMS 5625 C



Light Grey
PMS 422C



Light Tan
PMS 7536C



Navy
PMS 532C



Petrol Blue
PMS 2135C