

## SPEC SHEET + MEASUREMENTS



### Wink® Men's Long Lab Coat. WW5172

#### Product photo



- 65/35 poly/cotton poplin
- Locker loop
- Left chest pocket with pen slot
- Top-loading front pockets
- Interior tablet pocket
- Side seam opening for easy access to pants pockets
- Back yoke with pleats
- 4-button placket opening
- Center back vent
- Wink® heat transfer logo at left pocket
- Size medium: 42-inch back length

#### CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

#### Sketches



front



back

# SPEC SHEET + MEASUREMENTS



## Wink® Men's Long Lab Coat. WW5172

### PRODUCT MEASUREMENTS

|                      | XS     | S      | M      | L      | XL     | 2XL    | 3XL    | 4XL    | 5XL    |
|----------------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Body Length at Back  | 41     | 41 1/2 | 42     | 42 1/2 | 43     | 43 1/2 | 44     | 44 1/2 | 45     |
| Chest                | 42     | 45     | 48     | 51     | 54 1/2 | 58 1/2 | 62 1/2 | 66 1/2 | 70 1/2 |
| Pocket Height        | 5 1/2  | 5 1/2  | 5 1/2  | 6      | 6      | 6      | 6 1/2  | 6 1/2  | 6 1/2  |
| Pocket Width         | 5      | 5      | 5      | 5 1/2  | 5 1/2  | 5 1/2  | 6      | 6      | 6      |
| Set in Sleeve Length | 23 7/8 | 24     | 24 1/8 | 24 1/4 | 24 3/8 | 24 1/2 | 24 5/8 | 24 3/4 | 24 7/8 |

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Pocket Height:** Measure from top to bottom at center.

**Pocket Width:** Measure from side to side at top edge.

**Set in Sleeve Length:** Measure from Center Back neck to shoulder point to sleeve hem.

### SIZE CHARTS

|       | XS    | S     | M     | L     | XL    | 2XL   | 3XL   | 4XL   | 5XL   |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Chest | 34-35 | 36-38 | 39-41 | 42-45 | 46-49 | 50-53 | 54-57 | 58-60 | 61-64 |


# SPEC SHEET + MEASUREMENTS



Wink<sup>®</sup> Men's Long Lab Coat. WW5172

## HOW TO MEASURE

---



### CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## COLORS

---

Please note: PMS code information is shown only when an exact match is available.



White